

# Wiring Diagram

***WARNING:*** *DO NOT SERVICE WHILE ENERGIZED!*

MT-PML-R7-1P-GMR-50KVA-SZ-LT-DF-A6-BM-AZ-ZBZ-M1




| PRIMARY VOLTS | |
|---|---|
| CONNECT LINES TO H1A, H1B | |
| TAP | VOLTAGE |
| 1 | 7565 |
| 2 | 7380 |
| 3 | 7200 |
| 4 | 7020 |
| 5 | 6845 |
| **SECONDARY VOLTS** | |
| CONNECT LINES | VOLTAGE |
| X1, X3 | 240 |
| X1, X2 - X2, X3 | 120 |







LARSON ELECTRONICS LLC • 9419 E US HWY 175 • KEMP, TX 75143
p: 1-800-369-6671 • intl: 903-498-3363 • f: 903-498-3364 • sales@larsonelectronics.com

# Wiring Diagram

MT-PML-R7-1P-GMR-50KVA-SZ-LT-DF-A6-BM-AZ-ZBZ-M1






LARSON ELECTRONICS LLC • 9419 E US HWY 175 • KEMP, TX 75143
p: 1-800-369-6671 • intl: 903-498-3363 • f: 903-498-3364 • sales@larsonelectronics.com