



Larson Electronics LLC

www.Magnalight.com

9419 E US HWY 175, Kemp, TX 75143 - P: (800) 369-6671 - F: (903) 498-3364 - E: sales@magnalight.com

EPLFL-26W-120

CORD ATTACHMENT INSTALLATION

When the lighting unit is supplied with cable only, the receptacle shall be a three-wire grounding type suitable for use in the same hazardous location classes and groups as the light unit.

The procedure for powder cord connection is as follows:

1. Loosen bottom set screw and remove cord bushing assembly.
2. Loosen set screw on the handle and unscrew from base of the light.
3. Pull cable through the cord bushing and put the cable through the bottom of the handle.
4. Attach the white, black, and green wires to the cord connection assembly. Make sure the set screws are firmly attached to the cables.
5. Re-attach the handle to the base of the light and tighten set screw.
6. Re-attach cord bushing assembly and tighten set screw.

GREAT CARE MUST BE EXERCISED IN CONNECTING THE POWER SUPPLY CORD TO THE CONNECTOR PLUG ON THE LIGHTING UNIT AND ATTACHEMENT PLUG CAP.

CHECK GROUND CONTINUITY BEFORE PLACING LIGHT IN SERVICE.