Industrial Aluminum Tripod - Extends from 3.5 to 10 feet

Instruction Manual

TRIPOD ASSEMBLY

The tripod assembly consists of 3 parts:

1. T-bracket
2. Extension Pole
3. Leg Base

To assemble quadpod:

1. Begin by placing the legs in a flat level area.
2. Extend the legs to hold up the tripod.
3. Loosen legs and slide down until fully deployed. Tighten hand screw.
4. Finally, attach T-bracket over the top Extension Pole and tighten hand screw.

Use appropriate measures to attach equipment to the top of T-bracket. Predrill holes through top and bottom and utilize bolts for mounting heavy equipment.

WARNING: *Use caution before tilting tripod with a heavy load. For heavy loads, it is recommended to remove the T-bracket prior to transporting! Failure to do so may cause serious injury. Larson Electronics shall not be held liable for injuries caused by misuse.*

1. Place tower in desired location that is flat and able to support the tripod without falling over.
2. Loosen hand screw and lower legs until firmly stabilizing tripod.
3. Tighten hand screw to secure legs.
4. With help, place the T-bracket over top pole and tighten hand screw.

Light weight devices can be attached by tilting tripod toward the ground with the legs up. Attach T-bracket to pole, tighten hand screw and tilt back to its vertical position. DO NOT tilt tripod while extended to max height. It is recommended to have another person hold the tripod while tilting vertically.

For heavy equipment, use a ladder and extra help for attaching T-bracket to pole.

Double check that all hand screws are tight before continuing use of the tripod tower.

EXTENDING

1. Loosen hand screw for extending the T-bracket.Once loose, extend T-bracket untildesired height is achieved with at least 1ft - 2ft remaining inside pole for support.

WARNING: *DO NOT over extend T-head completely allowing extension pole to free from base! If the T- bracket becomes free, serious injury or death can occur. Larson Electronics shall not be held liable for injuries caused by misuse.*

2. When desired height is achieved, tighten hand screw to secure T-bracket.

LOWERING

1. To lower mast, grasp T-bracketand slowly loosen hand screw. Lower the T- bracket and tighten hand screw.

WARNING: *DO NOT loosen hand screw allowing T- bracket to fall freely. This can damage the unit and cause serious injury or death. Always grasp T-bracket before lowering. Larson Electronics shall not be held liable for injuries caused by misuse.*

The tripod mount tower can be disassembled for storage or transporting. Unplug attached equipment from power source and remove T-bracket following previous steps for attaching.

Once the T-bracket has been removed, loosen hand screw for legs and fold them up. Wheel to desired location or remove from wheel base for complete disassembly.

The ALU-TP-158 is designed to provide years of reliable performance. Should the need for replacement parts arise, please contact Larson Electronics at the contact information below.

MAINTENANCE

1. Perform visual, mechanical and electrical inspections on a regular basis. We recommend routine checks to be made on a yearly basis. Frequency of use and environment should determine this.
2. Do not operate if any part of the quadpod is cracked or damaged. All fasteners should be properly seated.

REPLACEMENT PARTS

The ALU-TP-158 is designed to provide years of reliable performance. Should the need for replacement parts arise, please contact manufacturer. Some parts may be sourced locally from your nearby hardware store.

WARRANTY

Should further information not covered by these instructions be required, please contact Larson Electronics at 1-800-369-6671 or sales@larsonelectronics.com for further assistance.

Please visit LarsonElectronics.com for **Warranty** and **Return** information.