


Wiring Diagram

WARNING: DO NOT SERVICE WHILE ENERGIZED!

MMT-380V-1000VA-220V



High Voltage (HV)
(Primary)
380

Install Supplied Jumpers
Between Terminals
NONE

Input Lines
Connect to
2, 3

Low Voltage (LV)
(Secondary)
220

Install Supplied Jumpers
Between Terminals
3-4

Output Lines
Connect to
2, 5