
Wiring Diagram

WARNING: *DO NOT SERVICE WHILE ENERGIZED!*

MT-DOE16-3P-460D-300KVA-415Y.240-N3R

Wiring Diagram

Primary: 460 Volts Delta
Secondary: 415Y/240 Volts



Connections

Primary Volts	On Each Coil Jumper Taps To	Primary Lines Connect To
460	7	H1, H2, H3

Secondary Volts	Secondary Lines Connect To
415	X1, X2, X3
240 1 Phase	Between X0 and X1 or X2 or X3

LARSON ELECTRONICS LLC • 9419 E US HWY 175 • KEMP, TX 75143
p: 1-800-369-6671 • intl: 903-498-3363 • f: 903-498-3364 • sales@larsonelectronics.com