
Wiring Diagram

WARNING: *DO NOT SERVICE WHILE ENERGIZED!*

MT-ISX-3P-480Y-30KVA-400Y.231-N3R



PRIMARY VOLTS	
CONNECT LINES TO H1, H2, H3	
CONNECT TAPS	VOLTAGE
1	504
2	480
3	456
SECONDARY VOLTS	
CONNECT LINES TO	VOLTAGE
X1, X2, X3	400
X1, X0 | X2, X0 | X3, X0	231 - 1Phase

LARSON ELECTRONICS LLC • 9419 E US HWY 175 • KEMP, TX 75143
p: 1-800-369-6671 • intl: 903-498-3363 • f: 903-498-3364 • sales@larsonelectronics.com