
Wiring Diagram

WARNING: *DO NOT SERVICE WHILE ENERGIZED!*

MT-DOE16-SS-FP-1P-240.480V-0.75KVA-120.240V-N4X-CU



Primary Volts	Connect Lines To	Jumpers
480	H1-H4	H2-H3
240	H1-H4	H1-H3, H2-H4

Secondary Volts	Connect Lines To	Jumpers
240	X1-X4	X2-X3
120	X1-X4	X2-X4, X1-X3

LARSON ELECTRONICS LLC • 9419 E US HWY 175 • KEMP, TX 75143
p: 1-800-369-6671 • intl: 903-498-3363 • f: 903-498-3364 • sales@larsonelectronics.com