Wiring Diagram

WARNING: *DO NOT SERVICE WHILE ENERGIZED!*

MT-DOE16-FP-1P-120.240V-7.5KVA-120.208V-N3R



Primary Volts	Connect Lines To	Interconnect
120	X1-X4	X1-X3, X2-X4
120/240	X1-X3-X4	X2-X3
240	X1-X4	X2-X3

Secondary Volts	Connect Lines To	Interconnect
120	H1-H8	H1-H6, H3-H8
208	H1-H8	H2-H7
240	H1-H8	H3-H6
277	H1-H8	H4-H5

LARSON ELECTRONICS LLC • 9419 E US HWY 175 • KEMP, TX 75143
p: 1-800-369-6671 • intl: 903-498-3363 • f: 903-498-3364 • sales@larsonelectronics.com