



Wiring Diagram

WARNING: DO NOT SERVICE WHILE ENERGIZED!

MT-DOE16-1P-480V-500VA-110.220V-N3R

H1-H6: 480V +5%

H2-H6: 480V

H3-H6: 480V -5%

H4-H6: 480V -10%

H2-H5 240V

X1-X2: 110V

X1-X3: 220V